

Inspection / Service Report

Start date 11-31-20

Finish date 12-4-20

UNIT: 2017 BB12XP		
Vin# 4FMUS131XHR503166	Part Number	Serviced/Condition
Engine: GM 4.3L V6 gas	S# M0002107	Runs good
Oil : Castro Edge 5w-30 full syn	Carquest 85040	New
Belts	K868770	Good
Air Cleaner	Napa 6569/6562	Clean inner, new outer
Instruments		All Good/610 hrs
Coolant/Radiator	Orange	Full/ Cleaned radiator fins
Fuel Filter		Did not replace
Clutch	Auto Clutch HD1300G	Good
Battery		New 1 year old
Starter		Good
Hydraulics:		Good
Fluid/Filter	Napa 1551	New/topped off AW46
Hoses		Good
Machine:		Overall great shape
Blades/Teeth	Simonds #80852, 9x5.5x5/8	New
Bedknife		No adjustment needed
Bearings	Dodge pillow block	Repacked, good *
Structure		Sound, no issues
Belts		Good, original
Grease	Grey Molly	Yes
Trailer/ Frame:		Sound, no issues
Wheels	16" Steel 8 lug	Good
Tires	235/80R16 lr E	40%, 90%, 80 psi
Bearings	Dexter	Good/ Greased
Lights		Good, all work
Light plug	6 way commercial, extention	Good
Hitch/Chains		Good
* Dodge pillow block bearing need to be service every year or so. See manual.		
Right side brake was replace 10/20.		
Tested and video'd. Works great.		